

NOTE: REPAIR DETERIORATED

BEAM END - SEE BEAM

REPAIR NOTES

GENERAL NOTES

- I. REINFORCEMENTS TO EXISTING ROOFS ARE DESIGNED TO COMPLY WITH THE 2009 EDITION OF THE INTERNATIONAL BUILDING CODE AND "MINIMUM DESIGN LOADS FOR BUILDINGS AND OTHER STRUCTURES" BY THE AMERICAN SOCIETY OF CIVIL ENGINEERS (ASCET-05).
- A. GROUND SNOW LOAD PG= 100 PSF.
- B. SNOW LOAD IMPORTANCE FACTOR IS = 1.0
- C. EXPOSURE FACTOR CE = 1.0
- D. THERMAL FACTOR CT = 1.0
- E. FLAT ROOF SNOW LOAD PF = 72 PSF.
- F. SLOPED ROOF FACTOR AT GYM CS = 0.8
- G. SLOPED ROOF SNOW LOAD AT GYM PS = 56 PSF.
- DESIGN FOR SNOW DRIFTING, SLIDING, AND UNBALANCED SNOW LOADS COMPLIES WITH ASCET-05.
- 2.DIMENSIONS INDICATED AS "+/-" ARE TAKEN FROM EXISTING CONDITIONS. VERIFY WITH FIELD MEASUREMENTS PRIOR TO FABRICATION OR INSTALLATION OF AFFECTED PARTS OF THE WORK.
- 3.VERIFY ALL MEMBER SIZES AND SPACINGS PRIOR TO PROCEEDING WITH AFFECTED PARTS OF THE WORK.
- 4.REMOVE ANY ITEMS THAT OBSTRUCT THE INSTALLATION OF SPECIFIED REINFORCEMENTS. REPLACE AFTER STRUCTURAL REINFORCEMENT HAS BEEN INSPECTED. REMOVAL AND REINSTALLATION COSTS SHALL BE INCLUDED IN THE BID.
- 5.ALL STEEL WORK SHALL COMPLY WITH THE AMERICAN INSTITUTE OF STEEL CONSTRUCTION "SPECIFICATIONS FOR STRUCTURAL STEEL BUILDINGS", 2010 EDITION (AISC 360-10).
- 6.NO WELDING IS PERMITTED IN THE GYMNASIUM. ALL ATTACHMENTS SHALL BE DONE BY BOLTING, SCREWING, OR OTHER APPROVED METHODS.
- 7.STEEL PLATES AND ANGLES SHALL BE ASTM A36.
- 8.BOLTS FOR CONNECTING STEEL MEMBERS SHALL BE ASTM A325N, SIZE AS INDICATED OR REQUIRED TO SUPPORT DESIGN LOADS. FIELD TIGHTEN TO SNUG-TIGHT CONDITION PER THE "SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH-STRENGTH BOLTS" BY THE RESEARCH COUNCIL OF STRUCTURAL CONNECTIONS, 2009 EDITION.
- 9.CLEAN NEW STEEL TO SSPC SP3, POWER TOOL CLEANING, IN SHOP. APPLY SHOP PRIMER, TNEMEC 10-99 FROM THE RIGHTER GROUP OR EQUAL TO A MINIMUM DRY FILM THICKNESS OF 2.0 MILS.
- IO. INSTALL FINISH PAINT THE SAME AS EXISTING IN 2 COATS.

BEAM REPAIR NOTES

- I. WHERE INDICATED, REPAIR DETERIORATED BEAM WITH EPOXY REPAIR FROM ABATRON, INC. OR EQUAL.
- 2.REMOVE ALL ROTTED WOOD. WHERE NECESSARY, REMOVE SOUND WOOD AS REQUIRED TO ACCESS ROTTED WOOD AT CORNER COLUMNS.
- 3.ALLOW WOOD TO DRY. REPAIRS MUST BE APPLIED TO DRY WOOD.

 4.THOROUGHLY MIX COMPONENTS OF LIQUIWOOD AT A 1:1 RATIO.

 COAT WOOD IN THE VICINITY OF THE REPAIR WITH LIQUIWOOD.
- COAT WOOD IN THE VICINITY OF THE REPAIR WITH LIQUIWOOD.

 APPLY IN COATS UNTIL SURFACE ATTAINS A SHINY APPEARANCE.

 FOLLOW THE MANUFACTURER'S SPECIFICATIONS FOR APPLICATION TEMPERATURE AND OTHER ASPECTS.
- 5. ALLOW LIQUIMOOD TO CURE PER MANUFACTURER'S SPECIFICATIONS.
- 6.APPLY WOODEPOX IN MULTIPLE COATS AS REQUIRED TO RETURN THE BEAM CROSS-SECTION TO ITS ORIGINAL DIMENSIONS.
 THOROUGHLY MIX WOODEPOX COMPONENTS TO A 1:1 RATIO AS SPECIFIED BY THE MANUFACTURER. ADHERE TO THE MANUFACTURER'S SPECIFICATIONS FOR APPLICATION
- MANUFACTURER'S SPECIFICATIONS FOR APPLICATION
 TEMPERATURES, THICKNESS OF APPLICATION, AND CURE TIME
 BETWEEN COATS. DISCARD ANY REMAINING WOODEPOX AFTER IT
 BEGINS TO HARDEN. APPLY WOODEPOX ONLY WHEN AT A FLUID
 CONSISTENCY.
- 7. ALLOW MOODEPOX TO FULLY HARDEN BEFORE INSTALLING ANY FASTENERS.
- 8.APPLY 2 COATS OF STAIN TO THE EXPOSED BEAM END. USE THE SAME STAIN AS EXISTING.

MOOD FRAMING NOTES

FOR THE HIGHEST CAPACITY.

- DIMENSIONED LUMBER SPECIFIED SHALL BE #2 OR BETTER,

 SPRUCE-PINE-FIR GRADED UNDER NLGA RULES.
- 2.ALL SUBSTITUTION REQUESTS SHALL BE APPROVED BEFORE INSTALLING.
- 3.WHERE FASTENING IS NOT SPECIFIED, PROVIDE FASTENING IN ACCORDANCE WITH TABLE 2304.9.I FROM THE 2009 EDITION OF THE INTERNATIONAL BUILDING CODE.
- 4.PROPRIETARY FRAMING CONNECTORS SHALL BE PRODUCTS FROM SIMPSON STRONG-TIE UNLESS OTHERWISE INDICATED. INSTALL WITH ALL FASTENERS RECOMMENDED BY THE MANUFACTURER UNLESS OTHERWISE NOTED. WHERE MORE THAN ONE FASTENING RECOMMENDATION EXISTS, INSTALL THE FASTENERS SPECIFIED
- 5.LAG SCREWS SHALL COMPLY WITH ANSI/ASME STANDARD BI8.2.I. WITH STEEL COMPLYING WITH SAE J429, GRADE I (MINIMUM YIELD STRENGTH = 36 KSI).
- 6.BOLTS SHALL COMPLY WITH ASTM A307, WITH THREADS IN COMPLIANCE WITH ANSI/ASME BI8.2.I.
- 7.WHERE NEW 2x6 ROOF PURLINS ARE SPECIFIED TO BE INSTALLED, FASTEN TO SUPPORTS THE SAME AS EXISTING, ADJACENT PURLINS.

CONNOR CONSOLIDATED SC

MICHAELIALAM MICHAELIALAM CUMMINGHAM NOMAS19

OID/HADE)
ing Associates, Inc
Street
Maine 04011

Engineering 6 Federal Stre Brunswick, Ma Phone: 207-729-

S1